

OFFICE ADDRESS:

10 Hon. Gideon Street, Off Peter Odili Rd T-Amadi, Port Harcourt.
 (Operations Tel: +234 (0)807 569 4478 + 234 (0)807 569 4467); (QA/QC Tel: +234 (0)807 569 4479)
 E-mail: info@mojustglobal.com, qaqc@mojustglobal.com Website: www.mojustglobal.com



Certificate of Thorough and Functional Examination


This report complies with the Lifting Equipment Engineers Association's technical requirements

Date of Thorough Examination: 26/07/2022	Date of Report: 26/07/2022	Report number: MGR/TV/07-22/059
---	-----------------------------------	--

Name and Address of employer for whom the thorough examination was made: TAMROSE LIMITED. Plot 7, Okuru-Abuloma Link Road, Abuloma, Port-Harcourt, Rivers State (TMC FALCON)		Address of premises at which the examination was made: F.L.T ONNE	
Description and identification of the equipment: MOORING ROPE (Polyester) Length: 45m x Dia: 50mm ID Number: TMC-MR 001	Safe Working Load(s): N/A	Date of manufacture if known: N/A	Date of last thorough examination: N/A
Make:			

Is this the first examination after installation or assembly at a new site or location? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Within an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>			

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE): NONE								
Is the above a defect which is of immediate danger to persons			YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)			YES by:					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none state NONE): NONE								
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Name & Qualifications of person making this report: ROSY DAVIES NIGERIA FACTORY ACT/ASNT LEVEL II, LEEA: FOU SPECIFICATION: BS EN 13411-6:2004	Name of person authenticating this report: ONOME OGBORU NIGERIA FACTORY ACT/ASNT LEVEL II, NSL, LEEA: FOU, LEG Signature:  Date: 26/7/22	Latest date by which next thorough examination must be carried out: 25/01/2023
Name and address of employer of persons making and authenticating this report: MOJUST GLOBAL RESOURCES LTD.		
STATUTORY INSTRUMENTS 1998 NO.2307.FACTORIES ACT CAP F1, L.F.N, 2004. Lifting Operations and Lifting Equip. Regulation 1998.		